


CORNER RECORD

Document Number CR 4391City of Unincorporated Castro ValleyCounty of Alameda, CaliforniaBrief Legal Description Found standard Alameda County monument on San Miguel Ave

CORNER TYPE

Government Corner ☐ Control ☒
Meander ☐ Property ☐
Rancho ☐ Other ☐
Date of Survey 09/13/2010

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☒

Corner – Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

County Street Project may disturb monument which has been preserved with staddle points as shown on the diagram on Page 2

In compliance with section 8771 of the Professional Land Surveyors Act this corner record is being filed to establish the position of an existing monument prior to street reconstruction.

A description of the physical condition of the monument as found and as set or reset:

SEE LEGEND (Page 2)

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on December 20 2010

Signed [Signature] P.L.S or R.C.E. No. L.S. 7905



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 12-14-2010

and examined and filed 1-11-2011

Signed [Signature] P.L.S or R.C.E. No. 5726

Title County Surveyor

County Surveyor's Comment _____



SB28W3

