


**CORNER RECORD**Document Number C.R. 884City of OaklandCounty of Alameda, CaliforniaBrief Legal Description Parcel B, Parcel Map No. 3820, Book 155, pages 55-56**CORNER TYPE**

Government Corner ☐ Control ☐  
 Meander ☐ Property ☒  
 Rancho ☐ Other ☐  
 Date of Survey March 17, 1997

**COORDINATES  
(Optional)**

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found standard city monuments in Westview Drive as shown on Parcel Map No. 3820

(155 M 55 - 56)

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

Found 1/2" rebar with plastic cap LS 3833 at northeast corner of Parcel B. Set 1/2"  
rebar with plastic cap LS 3833 at southeast corner of parcel and on property lines  
as shown.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with  
 the Land Surveyors' Act on April 15, 1997.


Signed Robert W. Wilson L.S. or R.C.E. Number LS 3833

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received 5-21-97 and examined  
 and filed 4-30-98

Signed Russell R. Penland, Jr.

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_

